

Docket No. 05-0407
Quality Exhibit 4.6

NORTH SHORE GAS
Report of Facility Damage

M.M. 8/13/04

001 04-118

Damage No. 084

NORTH SHORE GAS Report of Facility Damage

Owner of Damaged Facilities ☒ North Shore Gas ☐ Other (Explain) _____
Date of Damage 8-10-04 Time 12:30 ☐ AM ☒ PM
Address / Location 2180 Kipling Lane City / Town HIGHLAND PARK

Company CHICAGO LAND DRAINING INC. Company Causing Damage Quality Saw and Seal
If NSG, list crew members: Bridgeman 7600 W. 79th St. 60455
Address 225 TELSAR ROAD City/Town LAKE ZURICH
State ILL Zip 60047 Phone 847-550-9681
Operator BRIAN LEHR Supervisor _____
Damage Caused By: ☐ Backhoe ☐ Trencher ☐ Bore Machine ☒ Other CUTTING MACHINE
Type of Work being Performed CUTTING ROAD TO REPLACE PAVEMENT
What was Cause of Incident SERVICE LINE WAS NOT DEEP IN THE MIDDLE OF THE ROAD ONLY 8" IN

What Facilities Were Damaged
☒ Gas Service ☐ Plastic ☐ Steel Size: ☐ 5/8" ☒ 3/4" ☐ 1-1/8" ☐ 1-1/4" ☐ 2" ☐ Other _____
☐ Gas Main ☐ Plastic ☐ Steel Size: ☐ 2" ☐ 4" ☐ 6" ☐ 8" ☐ 12" ☐ Other _____
☐ Electric Cable ☐ Telephone Cable ☐ Cable TV ☐ Water
☐ Sanitary Sewer ☐ Sump/Drain Tile ☐ Storm Sewer ☐ Other _____
Depth of Facilities 8 Inches Repairs Made ☒ Yes ☐ No Customer Notified ☒ Yes ☐ No
Fire Department Response ☐ Yes ☒ No Police Department Response ☐ Yes ☒ No

Utility Locate Information
Was There a Request for Location of Utility: ☒ Yes Date 8-4-04 Julie No. A2172769 ☐ No
Was Utility Located ☒ Yes Date 8-10-04 NSG Locator Name BROGIONI ☐ No
ON GOING PROJECT (If applicable)
Were Marks/Markers Intact After Damage ☒ Yes ☐ No
Was Utility Properly Located ☒ Yes ☐ No If No, How Far Off _____ Inches

Repairs Made By <input type="checkbox"/> Distribution <input type="checkbox"/> Service							
Date	Distribution Employees	ST	OT	Date	Service Employees	ST	OT
8-10	MERKLING	2 1/2	1	8/10/04	860/C. Ross	1 1/2	
8-10	LANGE	2 1/2	1	8/10/04	923/Ramos Ralfo	1 1/2	
8-10	LUPE		1 1/2				

Silarski

Material Used

Quantity	Size	Description
1	3/4"	2 BOLT SLEEVE

Photos Taken

☒ Yes

☐ No

Should Damaging Party be Billed

☒ Yes

☐ No

Explain

CONTRACTOR

SAW CUTTING ROAD SHOULD HAVE TEST HOLED GAS LINE TO FIND DEPTH AND LOCATION OF SERVICE. CONTRACTOR DOING SAW CUTTING. WAS WORKING FOR CHICAGO LAND PAVING. THEY DID NOT HAVE LOCATES.

Date Report Submitted

8-12-04

Submitted By

Silarski

Department

DIST

Supervisor

Silarski

Manager

Silarski

*Remember to include ALL Company Work Tickets, Time Tickets, JULIE Locale Tickets, Film, etc. with form